



Referendum Question 1: Elizabeth Haddon

Building Envelope

- All proposed exterior masonry and wood trim repairs
- New windows and doors in pre-2000s wings, incl. lintel restoration and door hardware and electrical prep for future installation of controlled access devices

Site Work

- Rainwater drainage upgrades (1913, 1952 wings)
- Barrier-free accessible route upgrades, incl. signage, sidewalks, and student drop-off

Special Systems

- Intercom, telephone, master clock, and data system upgrades

HVAC

- Replacement of (3) multi-purpose room roof top units
- Boiler upgrades, incl. burner gas train components, indoor/outdoor reset controls, and chimney repairs and liner restoration (excl. automatic controls)