



Referendum Question 1: Central/HMS

Building Envelope

- New modified bitumen roof, incl. roof deck repair and related work (1964 wing)
- All proposed exterior masonry and wood trim repairs, incl. portico
- Skylight removal, incl. ceiling/lighting replacement and plaster repairs at MS rotunda (1964 wing)

Site Work

- Repairs to exterior concrete steps, cheek walls, railings, and sidewalks (1964 wing)
- Barrier-free accessible route and site upgrades, incl. widening of sidewalk along Lincoln Ave. for student drop-off

Special Systems *(same as Haddon and Tatem)*

- Intercom, telephone, master clock, and data system upgrades

HVAC

- Installation of A/C in MS cafeteria
- Boiler upgrades (excl. automatic controls)
- Chimney repairs and liner restoration